Noise swash PCB v2.2

"Big Diagram"





Mounting:

Pots and switches are mounted on the SOLDER SIDE
Everything else is mounted on the COMPONENT SIDE

Jumpers:

The stomp gets a jumper.
If no low power mod, do a jumper (shown on diagram).
If no Tame/trouble mod, do two jumpers (shown on diagram).
If no self-osc flip/stomp mod, use a *1M w/switch* pot for self-osc, and run wires from (A) and (B) on the board to the 1M's switch.